


CONTROL RECEIVER
AUDIO INPUT/ OUTPUT



Control Receiver Interface




LINK COMMUNICATIONS, INC.

899 Parkway Lane, Billings, Montana 59101

PHONE: (406) 245-5002 FAX: (406) 245-4889


DRAWING	DATE	REVISION	SHEET
RLC-Club Deluxe II	Tuesday, August 06, 2002	C	1



DTMF / COR-PL / INPUT AND OUTPUT

LC LINK COMMUNICATIONS, INC.
 899 Parkway Lane, Billings, Montana 59101
 PHONE: (406) 245-5002 FAX: (406) 245-4889

DRAWING RLC-Club Deluxe II	DATE Tuesday, August 06, 2002	REVISION C	SHEET 2
-------------------------------	----------------------------------	---------------	------------




- AUD0 - Port 1 Receiver
- AUD1 - Port 2 Receiver
- AUD2 - Port 3 Receiver
- AUD3 - Port 4 Receiver
- AUD4 - Port 5 Receiver
- AUD6 - Autopatch Receiver
- AUD5 - DVR Audio/Port 6 Receiver
- AUD7 - Voice Synthesizer Audio




LINK COMMUNICATIONS, INC.
 899 Parkway Lane, Billings, Montana 59101
 PHONE: (406) 245-5002 FAX: (406) 245-4889

DRAWING	DATE	REVISION	SHEET
RLC-Club Deluxe II	Tuesday, August 06, 2002	C	3

AUDIO INPUT/O OUTPUT



AUDIO TEST POINTS




Radio Interface Page





LINK COMMUNICATIONS, INC.
 899 Parkway Lane, Billings, Montana 59101
 PHONE: (406) 245-5002 FAX: (406) 245-4889


DRAWING	DATE	REVISION	SHEET
RLC-Club Deluxe II	Tuesday, August 06, 2002	C	4



RLC-DVR INTERFACE



Tone/DVR/LED



Front Panel LED Display

LC LINK COMMUNICATIONS, INC.
 899 Parkway Lane, Billings, Montana 59101
 PHONE: (406) 245-5002 FAX: (406) 245-4889

DRAWING	DATE	REVISION	SHEET
RLC-Club Deluxe II	Tuesday, August 06, 2002	C	5